


Impacto del cambio climático en los recursos marinos y costeros de Puerto Rico



Ruperto Chaparro, Director
Programa Sea Grant
Universidad de Puerto Rico







































Castillo San Felipe del Morro
A UNIT OF
SAN JUAN NATIONAL HISTORIC SITE
U.S. DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

No Parking
No Exceptions

26











Carretera
PRIVADA
Transite a su
propio riesgo

CALLE SIN SALIDA

DEAD END















ARENERO RH
BO. GUAYABOS
ISABELA
PERMISO NO:
0-CT-PFE01-SI-00161-17022009



6.27. Gabion wall unwisely built in Rincón. The recreational beach is narrowing in front of the wall, which is already experiencing backwall scouring. A gabion wall is a poor choice for ocean shorelines because the mesh will quickly corrode and break, allowing the stone fill to spill out onto the beach, creating an unsightly hazard for beach users.

measure was ineffective, however, and 50-year-old garbage continues to spill into the sea. The truth will continue to become evident as neighboring beaches begin to erode and the tourist-based economy of the area suffers. Users of the marina should share the costs of periodic dredging to lessen the environmental impact.

Punta Higüero to Río Grande (municipio























Para más información contacta al:
787 • 887 • 2000
787 • 885 • 5000

Ya no es
un sueño.
Primeras residencias
de Coco Beach.



PELIGRO
PROHIBIDO EN
CONSTRUCCION

**NO ENTRE SIN
AUTORIZACION**















Antes de muro



































